



TEST REPORT

100 Clemson Research Blvd.
Anderson, SC 29625
(864) 656-1094
Fax: (864) 656-1095
www.brickandtile.org

Results of Tests on brick Conducted in accordance with ASTM C 67-18 Standard Test Methods for Sampling and

Testing Brick and Structural Clay Tile

12/02/2019

Name:	Yankee Hill Brick 3705 South Coddington Avenue Lincoln , NE 68522	Plant:	Yankee Hill Brick	*Temperature: 60 - 90F
Phone:	402-770-7720	Report Number:	9232-22015	*Humidity: 30% - 70%
Fax:		Received Date:	11/12/2019	
		Sampled Date:	11/12/2019	
		Lot:		
		Product Code:		

Sample Description: **Medium Red**

							Test Date
Absorption		1	2	3	4	5	Average
24 Hour Submersion in Cold Water (%)		5.03	4.97	4.62	5.34	4.66	4.93 11/14/2019
5 Hour Submersion in Boiling Water (%)		7.54	7.38	7.01	7.67	7.01	7.32
Saturation Coefficient (Ratio of 24H to 5H)		0.67	0.67	0.66	0.70	0.66	0.67
Compressive Strength		1	2	3	4	5	Average
	<i>psi</i>	16,455	8,430	14,089	14,928	9,011	12,582 11/14/2019
	<i>MPa</i>	113.5	58.1	97.1	102.9	62.1	86.8
Efflorescence		11	12	13	14	15	
		Not Effloresced	Not Effloresced	Not Effloresced	Not Effloresced	Not Effloresced	11/22/2019
IRA (Oven Dried Method)		6	7	8	9	10	Average
	<i>g/min/30 in.²</i>	9.4	10.3	8.5	9.3	9.6	9.4 11/20/2019
Average % Void		20.8					11/20/2019

The brick represented by the test results shown here comply with the physical property requirements of the standards listed below:

ASTM C 216 - 17a Standard Specification for Facing Brick (Solid Masonry Units Made From Clay or Shale)

Grade: SW, MW

Michael Walker, Quality Manager

**The temperature and humidity of the Bishop Materials Laboratory is constantly kept between 60 -90F, and 30-70% RH*

The results shown above apply only to the samples tested, which are provided by the customer.

This test report shall not be reproduced except in full, without written approval of the laboratory.

TEST REPORT

100 Clemson Research Blvd.
Anderson, SC 29625
(864) 656-1094
Fax: (864) 656-1095
www.brickandtile.org



Results of Tests on brick Conducted in accordance with C67/C67M - 23 Standard Test Methods for Sampling and Testing Brick and Structural Clay Tile

08/25/2023

Name:	Yankee Hill Brick 3705 South Coddington Avenue Lincoln, NE 68522	Plant:	Yankee Hill Brick
Phone:	402-770-7720	Sampled Date:	8/8/2023
Report Number:	11942-29731	Received Date:	8/8/2023
		Fired Date:	8/8/2023
		Product Code:	
		Lot Number:	
Description: Dark Red / Maroon			

Absorption	1	2	3	4	5	Average	Test Date
24 Hour Cold Water (%)	2.6	2.6	2.6	2.9	2.5	2.6	8/10/2023
5 Hour Boiling Water (%)	4.4	4.6	4.5	4.6	4.6	4.5	
Saturation Coefficient	0.60	0.56	0.58	0.63	0.56	0.59	

Compressive Strength	1	2	3	4	5	Average	Test Date
psi	15,440	18,050	14,890	14,510	15,670	15,710	8/10/2023

IRA (Oven Dried Method)	6	7	8	9	10	Average	Test Date
g/min/30 in. ²	2.8	3.3	3.2	2.7	2.5	2.9	8/21/2023

Efflorescence	11	12	13	14	15	Test Date
Efflorescence Detection	Not Effloresced	Not Effloresced	Not Effloresced	Not Effloresced	Not Effloresced	8/21/2023

Void Area	1	2	3	4	5	Average	Test Date
Void Area (%)	21	21	21	21	21	21	8/18/2023

The brick represented by the test results shown here comply with the physical property requirements of the standards listed below:

ASTM C216 - 22 Standard Specification for Facing Brick (Solid Masonry Units Made From Clay or Shale)
Grade: SW, MW

Katherine Hill
Katherine Hill, Quality Manager

**The temperature and humidity of the Bishop Materials Laboratory is constantly kept between 60 -90F, and 30-70% RH
The results shown above apply only to the samples tested, which are provided by the customer.
This test report shall not be reproduced except in full, without written approval of the laboratory.*